

### Vehicle Inspection Report

Date Inspected: 26/03/2019 10:54  
Inspected By:

**Reg:** LRZ8519

**VIN:** VF77DBHY6GJ867956

### Valuation

**Cap Clean** £7600  
**Cap Average** £7175

### NAMA Grading



Grade

**4**

Appraised By: David Scott

### General Details

<b>Make</b>	Citroen	<b>Transmission</b>	Manual
<b>Model</b>	Berlingo 1.6 BlueHDi 850kg Enterprise	<b>Gears</b>	5
<b>Body Type</b>	Van	<b>Date First Reg</b>	10/02/2017
<b>Mileage</b>	35,774 miles	<b>Doors</b>	3
<b>Fuel Type</b>	Diesel	<b>Colour</b>	White
		<b>Year of MFR</b>	2017

### Tyres & Wheels

<b>OSF Depth</b>	1	<b>Wheel Trims</b>	Average
<b>NSF Depth</b>	4	<b>Alloys</b>	No
<b>OSR Depth</b>	3	<b>Spare</b>	Space Saver
<b>NSR Depth</b>	3	<b>Tyre Comments</b>	

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Odour</b>	No
<b>Comments</b>	

### Miscellaneous

**V5** B/T/A £150  
**Location** charge  
**No. Keys** 2


### Extras

<b>Interior</b>	Cloth	<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Xenons</b>	No
<b>Seats</b>	Manual	<b>Climate</b>	No	<b>Front Park Assist</b>	No		
<b>Cruise Control</b>	Yes	<b>Sat Nav</b>	Yes	<b>Rear Park Assist</b>	Yes		

### Service History

**Service History**  
**Stamps** 2

Photos



Damage Assessment



**Bumper Front**

Scratched  
Over 100mm  
Thru Paint  
Refinish



**Wing nsf**

Dented  
Over 30mm  
Repair and  
Refinish



**Door nsr**

Dented  
With Paint  
Damage  
Repair and  
Refinish



**Qtr Panel nsr**


Poor Previous  
Repair  
Poor Paint  
Refinish



**Qtr Panel osr**

Dented  
With Paint  
Damage  
Repair and  
Refinish

Vehicle Splat



Splat Key

- S2**  
Scratch/Paint defect 30-100mm
- S3**  
Scratch/Paint defect 100mm +
- D1**  
Dent/damage under 30mm
- D2**  
Dent/damage 30-100mm
- D3**  
Dent/damage 100mm +
- C2**  
Multiple Chips
- PP**  
Poor Previous

Comments

---