

### Vehicle Inspection Report

Date Inspected: 25/09/2019 08:17  
Inspected By:

**Reg:** KGZ1227

**VIN:** VF7SXHMZ6JT576891

### Valuation

**Cap Clean** £7300  
**Cap Average** £6775

### NAMA Grading



Grade

**3**

Appraised By: David Scott

### General Details

<b>Make</b>	Citroen	<b>Transmission</b>	Manual	<b>Taxi/PH</b>	No
<b>Model</b>	C3 Flair 1.2 Puretech	<b>Gears</b>	5		
<b>Body Type</b>	Hatchback	<b>Date First Reg</b>	31/05/2018		
<b>Mileage</b>	27,927 miles	<b>Doors</b>	5		
<b>Fuel Type</b>	Petrol	<b>Colour</b>	Beige		
		<b>Year of MFR</b>	2018		

### Tyres & Wheels

<b>OSF Depth</b>	1	<b>Wheel Trims</b>	
<b>NSF Depth</b>	3	<b>Alloys</b>	Yes
<b>OSR Depth</b>	4	<b>Spare</b>	Space Saver
<b>NSR Depth</b>	6	<b>Tyre Comments</b>	

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Odour</b>	No
<b>Comments</b>	

### Miscellaneous

**V5** B/T/A £150  
**Location** charge  
**No. Keys** 2

### Extras

<b>Interior</b>	Cloth	<b>Air</b>	Yes	<b>Sun Roof</b>	No	<b>Xenons</b>	No
<b>Seats</b>	Manual	<b>Conditioning</b>		<b>Front Park Assist</b>	No		
<b>Cruise Control</b>	Yes	<b>Climate</b>	Yes	<b>Rear Park Assist</b>	Yes		
		<b>Sat Nav</b>	No				

### Service History

**Service History**  
Stamps

Photos



Damage Assessment



**Door nsr**


- Poor Previous Repair
- Poor Paint Refinish



**Wing nsf**

- Poor Previous Repair
- Poor Paint Refinish

Vehicle Splat



Splat Key

- S1** Scratch/Paint defect to 30mm
- D1** Dent/damage under 30mm
- C1** Single Chip
- PP** Poor Previous

Comments