

Vehicle Inspection Report

Date Inspected: 10/09/2019 14:40
Inspected By:

Reg: KRZ7675

VIN: YV1MV74L1G2345056

Valuation

Cap Clean £7700
Cap Average £7175

NAMA Grading



Grade

3

Appraised By: Belfast City

General Details

Make	Volvo	Transmission	Manual	Taxi/PH	No
Model	V40 2.0 D2 R-Design	Gears	6		
Body Type	Hatchback	Date First Reg	25/04/2016		
Mileage	60,191 miles	Doors	5		
Fuel Type	Diesel	Colour	Blue		
		Year of MFR	2016		

Tyres & Wheels

OSF Depth	5	Wheel Trims	
NSF Depth	4	Alloys	Yes
OSR Depth	3	Spare	Space Saver
NSR Depth	2	Tyre Comments	

Interior Condition

Carpets
Upholstery
Seats
Odour
Comments

Miscellaneous

V5 Location Here
No. Keys 2


Extras

Interior	Half Leather	Air Conditioning	Yes	Sun Roof	No	Xenons	Yes
Seats	Heated	Climate	Yes	Front Park Assist	No		
Cruise Control	Yes	Sat Nav	No	Rear Park Assist	Yes		


Service History

**Service No
History
Stamps**


Photos



Damage Assessment



Door osr
 Scratched
 Up To 25mm
 Thru Paint
 Smart Repair



Qtr Panel osr
 Scratched
 Up To 25mm
 Thru Paint
 Smart Repair




Wheel osr
 Scratched
 Over 50mm
 Smart Repair



Door nsr
 Scratched
 Up To 25mm
 Thru Paint
 Smart Repair



Wheel nsf
 Corroded
 Light
 Smart Repair



Bumper Front
 Poor Previous
 Repair
 Poor Paint
 Refinish



Bonnet
 Chipped
 Multiple Chips
 Refinish




Wheel osf
 Scratched
 Up To 50mm
 Smart Repair



Wheel nsr
 Scratched
 Over 50mm
 Smart Repair

Vehicle Splat



Splat Key

- S1**
Scratch/Paint defect to 30mm
- S3**
Scratch/Paint defect 100m +
- C2**
Multiple Chips
- PP**
Poor Previous
- R**
Rust

Comments

Empty text box for comments.