

## MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

### VEHICLE DETAILS

<b>Date</b>	April 2019
<b>Make</b>	Citroen
<b>Model</b>	Berlingo 1.6 BlueHDi 850kg Enterprise
<b>Registration</b>	LRZ8519
<b>Mileage</b>	35,774 miles

### ENGINE CHECKS

<b>Engine Runs Smoothly</b>	✓ OK
<b>No Excessive Smoking</b>	✓ OK
<b>Turbo</b>	✓ OK
<b>Clutch Slipping/Flywheel</b>	✓ OK
<b>Gear Change</b>	✓ OK
<b>Suspension</b>	✓ OK
<b>Brakes</b>	✓ OK

### WARNING LIGHT CHECKS

<b>EML Light Illuminated</b>	✓ No
<b>ABS Light Illuminated</b>	✓ No
<b>Airbag Light Illuminated</b>	✓ No
<b>Oil Warning Light Illuminated</b>	✓ No
<b>Servicce Indicator</b>	✓ No
<b>DPF Light Illuminated</b>	✓ No

### OTHER

<b>Roof/Sunroof</b>	✗ N/A
<b>Windows</b>	✓ OK
<b>Sat Nav</b>	✗ N/A
<b>Radio</b>	✓ OK
<b>Steering</b>	✓ OK