

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	April 2019
Make	Alfa Romeo
Model	Mito 0.9 Collezione Twinair
Registration	RIG5039
Mileage	21,767 miles

ENGINE CHECKS

Engine Runs Smoothly	✓ OK
No Excessive Smoking	✓ OK
Turbo	✓ OK
Clutch Slipping/Flywheel	✓ OK
Gear Change	✓ OK
Suspension	✓ OK
Brakes	✓ OK

WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Servuce Indicator	✓ No
DPF Light Illuminated	✓ No

OTHER

Roof/Sunroof	✗ N/A
Windows	✓ OK
Sat Nav	✓ OK
Radio	✓ OK
Steering	✓ OK