

## MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

### VEHICLE DETAILS

Date	March 2020
Make	Peugeot
Model	208 1.0 Access Plus
Registration	SNZ3169
Mileage	72,006 miles

### ENGINE CHECKS

Engine Runs Smoothly	✗ Issue
No Excessive Smoking	✓ OK
Turbo	✗ N/A
Clutch Slipping/Flywheel	✓ OK
Gear Change	✓ OK
Suspension	✓ OK
Brakes	✓ OK

### WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Service Indicator	✗ Yes
DPF Light Illuminated	✓ No

### OTHER

Roof/Sunroof	✗ N/A
Windows	✓ OK
Sat Nav	✗ N/A
Radio	✓ OK
Steering	✓ OK