

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	April 2019
Make	Audi
Model	Q7 3.0 TDi Quattro
Registration	VEZ6079
Mileage	147,810 miles

ENGINE CHECKS

Engine Runs Smoothly	✓ OK
No Excessive Smoking	✓ OK
Turbo	✓ OK
Clutch Slipping/Flywheel	✓ OK
Gear Change	✓ OK
Suspension	✗ Issue
Brakes	✗ Issue

WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Service Indicator	✓ No
DPF Light Illuminated	✓ No

OTHER

Roof/Sunroof	✓ OK
Windows	✓ OK
Sat Nav	✗ Issue
Radio	✓ OK
Steering	✓ OK