

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	October 2019
Make	Hyundai
Model	Amica 1.1 CDX
Registration	XKZ6453
Mileage	83,509 miles

ENGINE CHECKS

Engine Runs Smoothly	✓ OK
No Excessive Smoking	✓ OK
Turbo	✗ N/A
Clutch Slipping/Flywheel	✓ OK
Gear Change	✓ OK
Suspension	✗ Issue
Brakes	✓ OK

WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Servuce Indicator	✓ No
DPF Light Illuminated	✓ No

OTHER

Roof/Sunroof	✗ N/A
Windows	✓ OK
Sat Nav	✗ N/A
Radio	✓ OK
Steering	✓ OK