

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	May 2019
Make	Mercedes
Model	Citan 1.5 CDi 109 LWB
Registration	YFZ5949
Mileage	46,367 miles

ENGINE CHECKS

Engine Runs Smoothly	✓ OK
No Excessive Smoking	✓ OK
Turbo	✓ OK
Clutch Slipping/Flywheel	✓ OK
Gear Change	✓ OK
Suspension	✓ OK
Brakes	✓ OK

WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Servuce Indicator	✓ No
DPF Light Illuminated	✓ No

OTHER

Roof/Sunroof	✗ N/A
Windows	✓ OK
Sat Nav	✗ N/A
Radio	✓ OK
Steering	✓ OK