

Vehicle Inspection Report



OMAGH CENTRE

Reg: UHZ8522 CN: SALWA2KE9GA658604	Vat Status Standard (No Vat)	Vehicle Grade 2
---	--	---------------------------

Make: Land Rover	Fuel: Diesel	Date First Reg: 14/07/2016
Model: Range Rover Sport HSE SDV - 3.0	Transmission: Auto	Hand Controls: No
Engine Size: 2993	Gears:	Colour: Black
Engine No: 1058736306DT	Mileage: 40601	Wh Chair Adapt: No
Doors: 5	Yr of Manu: 2016	Sunroof: Panoramic
Body Type: Estate	Seats: 5	Parcel Shelf
Other:	Boot Mat: Yes	

Tyres	Interior Condition	Service History	Miscellaneous
Front Nearside: 4 mm	Carpets Front: Average	Service History: Yes	V5: Here
Front Offside: 4 mm	Carpets Back: Average	Last Service: 14/03/2019	MOT:
Rear Offside: 4 mm	Upholst Front: Average	Stamps: 2	TAX:
Rear Nearside: 4 mm	Upholst Back: Average	Mileage: 28993	Taxed To:
Spare: Yes	Seats Front: Average	Service Book: No	Master: No
Wheel Trims:	Seats Back: Average		Spare: Yes No. Keys: 2


Extras	Cruise Control:	F P Sens:	ABS:	D Airbag:
Interior: Leather	Yes	Yes	Yes	
Stereo: Auto CD	Pwr Steering: Yes	R P Sens: Yes	M Paint: Yes	Bluetooth Yes
SD Card: No	M Func S Wh: Yes	Alloy W: Yes	P Airbag:	Phone kit: No
H/Seats: Yes	Elec Windows: 4	C Lock: Yes	Sat Nav: Yes	
	Elec Mirrors: Yes	Other:		



Front Angle



Rear Angle



Interior



Speedo Reading

Damage Location	Fault	Damage	Qty
Wheel nsr	Scratched	Repair and Refinish	1
Door nsr	Chipped	PDR Smart Repair	1
Bonnet	Chipped	PDR Smart Repair	1
Door nsf	Chipped	PDR Smart Repair	1


EXTERIOR CONDITION	
X: Damage/Repl	R: Rust
D: Dent	C: Chipping
S: Scratch	MS: Multiple Scratch
P: Previous	K: Crack
PP: Poor Previous	L: Light Mark/Scratch



stone chips on bonnet



nsr door chips



Comments:

Print: Davy Boone

Date: 24/03/2020

Davy Boone



nsf door chips



nsr alloy scratched