



IMPORTANT NOTICE: CUSTOMER MUST SATISFY THEMSELVES THAT THE HEALTH CHECK IS AS STATED BY 5PM DAY AFTER SALE – NO EXCEPTIONS!

24 Gortrush Industrial Estate
Omagh
Co Tyrone
BT78 5EJ
Tel: 028 8224 1514

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	March 2020
Make	Vauxhall
Model	Corsa Excite AC CDTi Ecoflex - 1.3
Registration	NL14EGV
Mileage	116,874 miles

WARNING LIGHT CHECKS

EML Light Illuminated	<input checked="" type="checkbox"/>	No
ABS Light Illuminated	<input checked="" type="checkbox"/>	No
Airbag Light Illuminated	<input checked="" type="checkbox"/>	No
Oil Warning Light Illuminated	<input checked="" type="checkbox"/>	No
Service Indicator	<input checked="" type="checkbox"/>	No
DPF Light Illuminated	<input checked="" type="checkbox"/>	No

ENGINE CHECKS

Engine Running Smoothly	<input checked="" type="checkbox"/>	OK
No Excessive Smoking	<input checked="" type="checkbox"/>	OK
Turbo	<input checked="" type="checkbox"/>	OK
Clutch Slipping/Flywheel	<input checked="" type="checkbox"/>	OK
Gear Change	<input checked="" type="checkbox"/>	OK
Suspension	<input checked="" type="checkbox"/>	OK
Brakes	<input checked="" type="checkbox"/>	OK

OTHER

Roof/Sunroof	<input checked="" type="checkbox"/>	N/A
Windows	<input checked="" type="checkbox"/>	OK
Sat Nav	<input checked="" type="checkbox"/>	N/A
Radio	<input checked="" type="checkbox"/>	OK
Steering	<input checked="" type="checkbox"/>	OK