

### Vehicle Inspection Report

Date Inspected: 23/04/2019 15:53  
Inspected By: 01

**Reg:** GJ66VUU

**VIN:** WV1ZZZ7HZGH135603

### Valuation

**Cap Clean** £12100  
**Cap Average** £11200

### NAMA Grading



Grade

**4**

Appraised By: CAG Rockingham

### General Details

<b>Make</b>	Volkswagen	<b>Transmission</b>	Manual
<b>Model</b>	Transporter T28 SWB 2.0 TDi BMT 102	<b>Gears</b>	5
<b>Body Type</b>	Van	<b>Date First Reg</b>	11/10/2016
<b>Mileage</b>	42,134 miles	<b>Doors</b>	3
<b>Fuel Type</b>	Diesel	<b>Colour</b>	White
		<b>Year of MFR</b>	2016

### Tyres & Wheels

<b>OSF Depth</b>	Average	<b>Wheel Trims</b>	
<b>NSF Depth</b>	Average	<b>Alloys</b>	No
<b>OSR Depth</b>	Average	<b>Spare</b>	
<b>NSR Depth</b>	Average	<b>Tyre Comments</b>	

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Odour</b>	No
<b>Comments</b>	

### Miscellaneous

**V5 Location** T/F

### Extras

<b>Interior</b>	Cloth	<b>Air Conditioning</b>	No	<b>Sun Roof</b>	No	<b>Xenons</b>	No
<b>Seats</b>	Manual	<b>Climate</b>	No	<b>Front Park Assist</b>	No	<b>Towbar</b>	No
<b>Cruise Control</b>	No	<b>Sat Nav</b>	No	<b>Rear Park Assist</b>	No	<b>Keyless Entry</b>	No
<b>Bluetooth</b>	No						


### Service History

**Service No History Stamps**

Photos



## Damage Assessment



### Bonnet

Chipped  
Multiple Chips  
Refinish



### Tailgate

Dented  
Over 30mm  
Repair and Refinish



### Bumper Rear


Dented  
With Paint Damage  
Repair and Refinish



### Qtr Panel

Dented  
Over 30mm  
Repair and Refinish

## Vehicle Splat



## Splat Key

**S2**  
Scratch/Paint defect 30-100mm  
**D2**  
Dent/damage 30-100mm  
**C2**  
Multiple Chips

## Comments