

MECHANICAL CONDITION 18 POINT VEHICLE CHECK SHEET

VEHICLE DETAILS

Date	April 2019
Make	Peugeot
Model	108 1.2 PureTech Allure
Registration	MD66BTE
Mileage	15,532 miles

WARNING LIGHT CHECKS

EML Light Illuminated	✓ No
ABS Light Illuminated	✓ No
Airbag Light Illuminated	✓ No
Oil Warning Light Illuminated	✓ No
Serivce Indicator	✓ No
DPF Light Illuminated	✓ No

ENGINE CHECKS

Engine Runs Smoothly	✓ OK
No Excessive Smoking	✓ OK
Turbo	✗ N/A
Clutch Slipping/Flywheel	✗ Issue
Gear Change	✓ OK
Suspension	✓ OK
Brakes	✓ OK

OTHER

Roof/Sunroof	✗ N/A
Windows	✓ OK
Sat Nav	✗ N/A
Radio	✓ OK
Steering	✓ OK